

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 8 - 2012 Honda Odyssey



VIN 5FNRL5H40CB506310

Year 2012

Make Honda

Model Odyssey

Trim Level EX 4dr Mini-Van w/DVD

Engine 3.5l j35 VTEC

Transmission Automatic

Odometer 263,088

Odo Type KM

Color Silver

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Infotainment, Tilt, Roof Rails / Rack, Alum Rims, CD Player, Backup Camera, Cloth Interior, 3rd Row Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning Lights: TPMS (Tire Pressure Monitoring System) ON.

Location Fredericton NB - Jardine

Tires Front 7/32 rear 10/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 06/26

Plate Number (Jardine) JWV 790

MVI (Jardine) 06/26

Interior Comments (Jardine) Headliner/seats/floor stains

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left door rust specs/inner door rust, rear left fender dents/rust, trunk dents/rust, right rear fender

rust, right rear door paint bubbling/rust, front right door mirror cap broken/taped, windshield chips.

Exterior Condition (Jardine) Good

Description

CONSIGNOR DECLARES NEW BRAKES SPRING 2025, NEW SUMMER TIRES 2025, FRONT AXEL REPLACED 2025

[CARFAX; COLLISION CLAIM \\$6150, OTHER DAMAGE CLAIM \\$4090](#)

Vin 5FNRL5H40CB506310

Year 2012

Make Honda

Model Odyssey

Trim EX 4dr Mini-Van w/DVD

Engine 3.5l j35 VTEC

Transmission Automatic

Odometer 263,088, KM

Color Silver

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Infotainment, Tilt, Roof Rails / Rack, Alum Rims, CD Player, Backup Camera, Cloth Interior, 3rd Row Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning Lights: TPMS (Tire Pressure Monitoring System) ON.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 7/32 rear 10/32

Sales Status Red Light - Sold AS IS

Plate Date 06/26

Plate Number JWV 790

MVI 06/26

Interior Comments Headliner/seats/floor stains

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left door rust specs/inner door rust, rear left fender dents/rust, trunk dents/rust, right rear fender rust, right rear door paint bubbling/rust, front right door mirror cap broken/taped, windshield chips.

Exterior Condition Good

Quantity: 1

