

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 35 - 2011 Chevrolet Silverado 1500 4x2 Work Truck 4dr Extended Cab 8 ft. LB



VIN 1GCRCPE08BZ330502

Year 2011

Make Chevrolet

Model Silverado 1500

Trim Level 4x2

Body Subtype Extended Cab

Engine Vortec 5.3L Flex Fuel V8 315hp 335ft. lbs.

Transmission Automatic

Odometer 273 914

Odo Type KM

Color White

Declaration Vehicle Loud - Possible Exhaust Leak

Features (Jardine) Tilt, Hitch, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Not Functioning, Heat Functioning

Location Fredericton NB - Jardine

Tires Front 7/32, rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) None

Plate Number (Jardine) None

MVI (Jardine) 06/26

Interior Comments (Jardine) Headliner/seats/floor stains, seats tears. *AC not functioning.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left fender rust, front left door dents/rust/inner door/doorsill rust, rear left fender repainted, rear

bumper dents, tailgate dents/rust, right rear fender dents, right rear door dents, front right door dents/rust/inner door/doorsill rust, front right fender dents/rust, hood dents/rust, windshield crack chips.

Exterior Condition (Jardine) Good

Description

***AC not functioning, vehicle loud - possible exhaust leak**

[CLEAN CARFAX](#)

Vin 1GCRCPE08BZ330502

Year 2011

Make Chevrolet

Model Silverado 1500

Trim 4x2, Extended Cab

Engine Vortec 5.3L Flex Fuel V8 315hp 335ft. lbs.

Transmission Automatic

Odometer: 273 914, KM

Color White

Declaration Vehicle Loud - Possible Exhaust Leak

Features Tilt, Hitch, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Not Functioning, Heat Functioning

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 7/32, rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date None

Plate Number None

MVI 06/26

Interior Comments Headliner/seats/floor stains, seats tears. *AC not functioning.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left fender rust, front left door dents/rust/inner door/doorsill rust, rear left fender repainted, rear bumper dents, tailgate dents/rust, right rear fender dents, right rear door dents, front right door dents/rust/inner door/doorsill rust, front right fender dents/rust, hood dents/rust, windshield crack chips.

Exterior Condition Good

Quantity: 1

