


Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 74 - 2010 Nissan Titan



VIN 1N6AA0EC4AN312859

Year 2010

Make Nissan

Model Titan

Trim Level 4x4 SE 4dr Crew Cab SWB Pickup

Body Subtype Crew Cab

Engine 5.6L V8 317hp 385ft. lbs.

Transmission Automatic

Odometer 193 077

Odo Type KM

Color White

Declaration Engine Light On, Airbag Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Alum Rims, Hitch, Leather Interior

Air Conditioning / Heat (Jardine) AC Not Functioning, Heat Functioning

Comments Warning lights: Service engine soon, airbag light, caution light.

Location Fredericton NB - Jardine

Tires Front 11/32, rear 12/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 08/26

Plate Number (Jardine) CSG 876

MVI (Jardine) 07/26

Interior Comments (Jardine) Headliner/seats/floor stains. *AC not functioning.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, majority of vehicle repainted, front left inner door rust, rear left fender dents, right rear door dents, windshield chips.

Exterior Condition (Jardine) Good

Description

CLEAN CARFAX

Vin 1N6AA0EC4AN312859

Year 2010

Make Nissan

Model Titan

Trim 4x4 SE 4dr Crew Cab SWB Pickup, Crew Cab

Engine 5.6L V8 317hp 385ft. lbs.

Transmission Automatic

Odometer: 193 077, KM

Color White

Declaration Engine Light On, Airbag Light On

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Alum Rims, Hitch, Leather Interior

Air Conditioning / Heat AC Not Functioning, Heat Functioning

Location Fredericton NB - Jardine

Comments Warning lights: Service engine soon, airbag light, caution light.

In Yard Yes

Tires Front 11/32, rear 12/32

Sales Status Red Light - Sold AS IS

Plate Date 08/26

Plate Number CSG 876

MVI 07/26

Interior Comments Headliner/seats/floor stains. *AC not functioning.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, majority of vehicle repainted, front left inner door rust, rear left fender dents, right rear door dents, windshield chips.

Exterior Condition Good

Quantity: 1

