338168

INVOICE



RYSLER JEEP HAM MOPAR FIAT

230 Provincial Ave., Sherwood Park, AB T8H 0E1 00

Commence of	7 (K)		•		PAGE 1	Service Direct: (78 Body Shop: (780)		Service Fax: (78 Toll Free: 1-80	
HOME:		CONT:	THE THE PARTY				ww.sherwoodpar	kdodge.com	
BUS:		CELL: 7	- 80N - 79E	SERV	ICE ADVISOR	R: 875 RYA	N ROBERT	S	
COLOUR	YEAR	MAKE/MODE			VIN	LICENSE	ODOMET	ER IN/ OUT	TA
*	19	RAM TRUCKS	1500	1C6RR7	LGXKS5916	59	266209	/266209	T853
DEL DATE	PROD. D.	ATE WARR, EXP.	PROMISI	ED	PO NO.	RATE	PAYMENT	INV. D	ATE
03APR23 IS	3		17:00 15	NOV23		0.00	CASH	28NOV	2.3
R.O. OPEN	VED	READY	OPTIONS	DLR:	C8051 ENG	:3.6_Liter			
09:23 05SE	EP23	15:24 28NOV	723						
LINE OPCOL	DE TECI	H TYPE HOUR	S			LIST	' NE	T TO	TAL
RE	REPORTS ESTART Se tecl	S THE VEHIC - PCM REPI n story-cus				ND WOULD N	OT		
	3 5	5 IPS			2			(N	/C)
1		304AB MODUL 304AB MODUL	200 CO						/C) /C)
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL L	INE A:	0	.00

CHECK VEHICLE ON THE SCANNER FOR NO START AND PCM IS NOT ACTIVE ON THE COMMUNICATION BUS SYSTEM. WILL NEED TO GET VEHICLE PUSHED IN THE SHOP WHEN A BAY OPENS UP.

GET VEHICLE IN THE SHOP AND HOOK UP BREAKOUT BOX AND CHECK POWERS AND GROUNDS TO PCM AND LOAD TEST THESE CIRCUITS, OK. CHECK CAN C BUS CIRCUITS AND THEY HAD THE PROPER VOLTAGES. CHECK LIN BUS CIRCUIT, OK. CHECK FOR CORROSION UNDER PDC THAT COULD BE CAUSING PCM PROBLEM AND ALL CONNECTORS WERE OK. TALKED TO SERVICE MANAGER ABOUT VEHICLE. CHECKED ALL WIRES TO PCM FOR SHORT TO POWER OR GROUND AND THEY ALL APPEAR TO HAVE THE CORRECT VOLTAGE AND GROUND SIGNALS ON THEM. ORDER PCM FOR VEHICLE.

INSTALL NEW PCM AND PROGRAM SOFTWARE, VIN, MILEAGE AND CALIBRATE THROTTLE BODY. CYCLE THE KEY AND GO TO START VEHICLE AND IT TURNED OVER TWICE AND THEN QUIT AND PCM IS NOT ACTIVE ON THE BUS ANYMORE. UNHOOK ALTERNATOR FIELD WIRING AND STILL NOT ACTIVE. LEAVE POWER AND GROUND CONNECTOR PLUGGED IN AND CHECK TO SEE IF IT CAME BACK ONLINE, IT DID NOT. TALKED TO ADVISOR AND WILL TALK TO MANAGER WHEN HE GETS BACK. HOOK BREAK OUT BOX TO EACH PCM CONNECTOR AND RECORD VOLTAGE ON THE CIRCUITS AND THEY ARE ALL NORMAL. NOTHING STANDS OUT AS BAD. WIGGLE HARNESSES WHILE WATCHING VOLT METER ON SOME CIRCUITS AND SIGNALS DO NOT CHANGE. CONTACT TECH LINE TO SEE IF THEY HAVE SEEN ANYTHING LIKE THIS. ORDERED COILS AND NEW PCM. REMOVE UPPER INTAKE PLENUM AND REPLACE ALL IGNITION COILS. CHECK WIRING TO THE COILS, LOOKED OK. PUT ENGINE BACK TOGETHER AND INSTALL PCM. PROGRAM PCM TO THE VEHICLE AND VEHICLE CRANKED OVER BUT WOULD TRY TO FIRE BUT DID NOT START. AFTER A COUPLE OF TIMES THE PCM WENT OFFLINE AGAIN. CHECK HARNESS FOR SPOTS WHERE

#### **IMPORTANT**

YOU MAY RECEIVE QUESTIONNAIRE FROM CHRYSLER CORPORATION IN THE NEXT FEW DAYS. IF FOR ANY REASON YOU CAN NOT GRADE US "COMPLETELY SATISFIED" CONTACT GENERAL MANAGER.

THANK YOU

## DO YOU QUALIFY **FOR EXTENDED WARRANTY**

IF YOUR VEHICLE HAS NOT EXCEEDED 80,000 KM AND IS 3 YEARS OLD OR LESS YOU MAY STILL QUALIFY FOR AN EXTENDED WARRANTY.

> PLEASE ASK YOUR SERVICE ADVISOR FOR DETAILS.

# EXPERIENCE THE DIFFERENCE AT



I declare my indebtedness for the balance owing as shown on this invoice.

Date

Customer Signature

DESCRIPTION TOTALS LABOUR AMOUNT PARTS AMOUNT GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES TOTAL CHARGES LESS INSURANCE GST PLEASE PAY THIS AMOUNT

GST NO. 815150073 RT0001

338168

INVOICE



PAGE 2

CHRYSLER JEEP RAM MOPAR FIAT 230 Provincial Ave., Sherwood Park, AB T8H 0E1 Service Direct: (780) 410-4101 Service Fax: (780) 410-4118 Body Shop: (780) 410-4110 Toll Free: 1-800-317-5700

HOME:			CONT:	5 W - 4 W - 5	1		VVV	vw.snerwoodpark	aoage.com	
BUS:			CELL:		SER	VICE ADVISOR:	875 RYA	N ROBERTS	S	
COLOUR	YEAR	MAKE/MODEL			VIN		LICENSE	ODOMETER IN/ OUT		TAG
	19	RAM.	TRUCKS	1500	1C6RI	R7LGXKS591659		266209	/266209	T8539
DEL DATE	PROD.	DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. D.	ATE
03APR23 IS		,		17:00 1	5NOV23		0.00	CASH	28NOV	23
R O OPEN	ED	LE T	READY	OPTIONS	: DIJ	2.C8051 FNG.3	6 Titor			

DLR:C8051 ENG:3.6 Liter

15:24 28NOV23 09:23 05SEP23

LINE OPCODE TECH TYPE HOURS LIST TOTAL COULD BE GROUNDING OUT AND PULL APART HARNESS OVER COOLANT TUBES AND

FOUND A COUPLE OF WIRES THAT WERE RUBBED THROUGH. REPAIR THESE WIRES AND CHECK HARNESS FURTHER AND DID NOT SEE ANYMORE POSSIBLE PROBLEM AREAS. TALKED WITH SERVICE MANAGER AND ORDERED ANOTHER PCM. CONTACTED TECHLINE AGAIN. HEARD BACK FROM TECHLINE AND PERFORMED FURTHER TEST AS PER THEIR INFORMATION, COULD NOT PIN POINT PROBLEM, THEY SUGGEST REPLACING ENGINE HARNESS, EST ON REPAIRS. INSTALL ORIGINAL COIL BACK ON ENGINE.

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*\*

B TOW IN

MK MYKAARMA NO TEXT MESSAGES

999 CPG

0.00 0.00

PARTS:

0.00 LABOR: 0.00 OTHER:

0.00 TOTAL LINE B: 0.00

\*\*\*\*\*\*\*\*\*\*\*\*\*

\*IF YOUR WHEELS HAVE BEEN REMOVED PLEASE RETURN WITHING 150KMS FOR LUGNUT RETOROUE\* MOPAR PARTS WARRANTY IS 24 MONTHS/UNLIMITED MILEAGE FROM ORIGINAL INSTALLATION DATE. THIS INCLUDES PARTS & LABOUR. SOME EXCLUSIONS APPLY, SEE MOPAR.CA FOR DETAILS. NON-MOPAR PARTS CARRY MANUFACTURER COVERAGE.

### **IMPORTANT**

YOU MAY RECEIVE QUESTIONNAIRE FROM CHRYSLER CORPORATION IN THE NEXT FEW DAYS. IF FOR ANY REASON YOU CAN NOT GRADE US "COMPLETELY SATISFIED" ับร CONTACT PLEASE OUR GENERAL MANAGER.

THANK YOU

#### DO YOU QUALIFY **FOR EXTENDED WARRANTY**

IF YOUR VEHICLE HAS NOT IF YOUR VEHICLE HAS NOT EXCEEDED 80,000 KM AND IS 3 YEARS OLD OR LESS YOU MAY STILL QUALIFY FOR AN EXTENDED WARRANTY.

PLEASE ASK YOUR SERVICE ADVISOR FOR DETAILS.

# EXPERIENCE THE **DIFFERENCE AT**



I declare my indebtedness for the balance owing as shown on this invoice.

Customer Signature

Date

DESCRIPTION	TOTALS
LABOUR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
GST	0.00
PLEASE PAY THIS AMOUNT	0.00