

Wildens Service Ltd.

5521 - 3rd Avenue

Edson, AB. T7E 1L5

Phone: 780-723-4507 Fax: 780-723-4904

GST# - 105681159RT0001

INVOICE**44358**

Org. Est. # 064433

Invoice from History

Printed Date: 04/25/2022

Work Completed: 04/07/2020

2004 Buick - Rainier - 5.3L, V8 (325CI) VIN(P)

Lic # : BMJ 4580

Odometer In : 267504

VIN # : 5GAET13P5 42282403

Part Description	/ Number	Qty	Sale	Ext	Labor Description	Ext
------------------	----------	-----	------	-----	-------------------	-----

Org. Estimate	4,222.61	Revisions	0.00	Current Estimate	4,222.61
---------------	----------	-----------	------	------------------	----------

Labor:	1,020.00
Parts:	2,870.71
Sublet:	125.82
HazMat:	5.00

SubTotal:	4,021.53
Tax:	201.08
Total:	4,222.61
Bal Due:	\$0.00

[Payments - Visa - \$4,222.60, Service Charge Write Off - \$0.01]

Vehicle Received: 4/06/20

Customer Number : 116

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is as per manufacturer. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

RETORQUE WHEELS AFTER 100KM

Signature _____ Date _____

Email Address: wildens2@telus.net