## Authoriz:

Description 2009

Make Ford Truck F350 Super Duty P/u

Engine V10-415 6.8L SOHC

Odometer 146,701

VIN 1FTWW31Y99EB21494

PO # N/A

Work Order # 0000018878

Invoice # N/A

Svc Advisor Dwaine

Technician DL

## Services Requested

## Lube Oil & Filter

Change engine oil and filter. Change air filter.

Invoice Date Sep 06 2022

Appointment Sep 02 2022 8:00 am

Promised Sep 02 2022 6:00 pm

Technical Service Rate Premium Engine Oil 5W30 Oil Filter

.45 hrs. 7.00 Litres \$54.00 G\*

\$54.25 G \$7.50 GE

Air Filter

\$27.44 G

## Comment

Vehicle manufacturers recommend you have a maintenance inspection performed every 8000 km. Tire inspection and rotation is recommended every second oil change. A complete vehicle inspection should be performed once a year much the same as going

arker Bulbs			40
	ıb 🧓	\$143.19	
ange marker bulbs.	A 7457	6 . 35 . S	
Technical Service Rate .25 hrs.		\$30.00	
Bulb 2.00 Units	*	\$2.00	
Bulb 2.00 Units		\$2.00	G
St	ıb.	\$34.00	
haust / 5			
pair exhaust. Remove Y pipe and weld broken flayge on right hand side. Reassemble and install new	hanger, **	**NOTE!	
haust pipe is thin and if problem reoccurs a new/crossover pipe will be required.	7/40		
Technical Service Rate / 3.30 hrs.		\$396.00	G
Exhaust Clamp		\$8.68	G
Exhaust Hanger		\$29.60	G
Sı	ıb	\$434.28	
nk Wiring		\$ 15 HZC	
quire tank wiring for AUX tanks to up filter switches. Switch 1; Rear tank, Switch 2: Front Tank, Swit	ch 3. Work	cliahts.	
Technical Service Rate 3.00 hrs.	ch S. Work	\$360.00	G
Fuses 4.00 Units		\$4.00	
Butt Connectors 16.00 Units		\$15.36	
Wire Cable 16ga 16.00 Units		\$18.72	
	· <del>=</del>		
\	ΙÞ	\$398.08	
ash \			
ash rads and coolers.	M 12 2	+00.00	_
Technical Service Rate		\$30.00	ુઉ
Su	ıb g	\$30.00	
\		9	
Total Labor		\$870.00	
Total Parts		\$169.55	
			2
	\$	1,039.55	
Total Before Taxes & Miscellaneous Charges		\$34.80	_
/ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		4 54 XII	G
(*) Shop Supplies		451100	_
(*) Shop Supplies		,	
(*) Shop Supplies (E) Environmental Disposal Charge \$1.95 Each		\$1.95	G
(*) Shop Supplies	V	,	G

e-transfer: edgeautorepair@telus.net G.S.T. 803767821RT0001 VEHICLE REPAIR ORDER/INVOICE

il.com

se (CASH)

Vehide	<b>2009 Ford F-350 Super Duty FX4</b> 6.8 GAS - White 1FTWW31Y99EB21494				L a A	Miles In: Miles Out: icense Plate: E	135,038
Work Performed	Parts						
	Parts 4 NEW TIRES 265 70 17, SPARK PLUGS, AIR & CABIN FILTER, TWO FRONT SHOCKS, COIL PLUG BOOT, 2 OXYGEN SENSOR, EXHAUST MANIFOLD GASKET	Part No AAA1001		Qty 1.00	Price 1,945.00	Į.	Total 1,945.00
	WANTOLD GASKET				Parts	SubTotal	\$1,945.00
F 0	Labor	4 ( 9	3%	α <sup>c</sup>			
	Labor Mechanical Labor , SPARK PLUGS , AIR & CABIN FILTER , TWO FRONT SHOCKS , COIL PLUG BOOT , 2 OXYGEN SENSOR , EXHAUST MANIFOLD GASKET	. 4	Tech	Hrs 11.00	Price 100.00	¥	Tota 1,100.00
-					Labor	SubTotal	\$1,100.00
	Labor	3.0	ij			- 2	
	Labor WINDSHIELD REPAIR		Téch	Hrs 1.00	Price 220.00	_	Total 220.00
	Syn oil Change & Filter 6cl			1.00	120.00		120.00
	Install & Balance Tire			4.00	24.99		99.96
				1994	Labor	SubTotal	\$439.96
	Labor		9				50
	Labor Body Repair REPAIR RUSTS , PAINT & REFINISH ON BOTOM OF FOUR DOORS IN SIDE & OUT	3	Tech	Hrs 14.00	Price 75.00		Total 1,050.00
	SIDE						
					Labor	SubTotal	\$1,050.00
Total	2					Labor Parts Hazmat*	2,589.96 1,945.00 16.00
22		25 50	e in			Supplies* GST/HST	60.00
				1/2		.PST	0.0

Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste remova