

- Ford Transit
- Sleeps 2
- Seat Belts - 4
- V6 Petrol / Diesel Engine - Tank 95 litres
- Auto Transmission
- Cruise Control / Power Steering / Brakes
- AM / FM Radio with CD Player
- Dashboard Air Conditioning
- Roof Air Conditioning (select models)
- Stove / Microwave / Convection Oven
- Fridge
- Furnace
- Shower & Flush Toilet
- Reversing Camera
- Hot Water Heater
- Propane Tank - 22 litres
- Black Water - 57 Litres
- Grey Water - 57 Litres
- Fresh Water Tank - 75 Litres
- Dual Battery
- Generator
- Dinette Bed 1.06m x 1.82m (select models only)
- Rear Bed: 1.72 x 1.97m
- Overall Length 6.75m
- Overall Width 2.10m
- Overall Height 3.05m
- Interior Height 1.95m
- Awning **ELECTRIC -**

All measurements are approximate and floorplans are subject to change

Other Vehicles

Okanagan Tribute Van Conversion - 2 Berth	C Large RV / Slideout - 5 Berth
10ft Truck Camper / Bunk - 3+2 Berth	C XLarge RV - 6 Berth
10ft Truck Camper - 3 Berth	Overlander Motorhome - 6 Berth
10ft Truck Camper / Slideout - 2+2 Berth	A Class 30ft Motorhome Wheelchair - 5 Berth
C Small RV - 4 Berth	A Class 30ft Ace Motorhome - 6 Berth
C Medium RV - 5 Berth	

2018 OKANAGAN TRIBUTE, 22 foot CLASS B.
 FORD, TRANSIT CHASSIS, TURBO DIESEL.
 67,600 Kms. Completely Mechanically Certified.
 AS NEW. ——— PASS SEAT SWIVELS.
 BATTERY BOOST.
 ADDS: NAV...
 SAT. RADIO READY...
 BACKUP CAMERA...
 SPARE TIRE...

PARTS:	193.13
LABOUR:	242.22
OTHER:	4.68
SUB-TOTAL:	440.03
GST/HST:	22.01
PST:	N/C
TOTAL:	462.04

MOTOR VEHICLE RECORD OF INSPECTION

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Vehicle Information																	
VIN	1	F	T	B	W	3	X	V	0	J	K	A	3	9	8	5	1

Make Ford	Model TRANSIT	Year 2018	Odometer 67257
--------------	------------------	--------------	-------------------

Customer Information			
Last Name		First Name	
Address 11 HARMONY COURT WEST			Postal Code T7Z2A6

Section 1 - Pre-Inspection									
Component	P	F	NA	Component	P	F	NA		
1.1a. Request for Inspection (RFI)	✓			1.3c. Vehicle Wanders or Pulls	✓				
1.1b. Vehicle Accurately Described On The RFI	✓			1.3d. Brake System Performance	✓				
1.2a. VIN Plate Condition	✓			1.3e. Driveability	✓				
1.2b. VIN Consistent With RFI	✓			1.3f. Speedometer Operation	✓				
1.3a. CV Joint Road Test Result			✓	1.3g. Odometer (if equipped) Operation	✓				
1.3b. Universal Joint Road Test Result	✓								

NOTES:

Section 2 - Onboard Diagnostic Systems													
Component				P	F	NA	Component				P	F	NA
2.1a. PCM Codes Present				✓			2.4b. SRS Lamp Fails To Illuminate				✓		
2.1b. PCM (MIL, SES, etc) Lamp Fails To Illuminate				✓			2.4c. SRS Lamp Remains Illuminated				✓		
2.2a. ABS Codes Present				✓			2.4d. Airbag(s) Present				✓		
2.2b. ABS Lamp Fails to Illuminate				✓			2.4e. Airbag Cover Integrity				✓		
2.2c. ABS Lamp Remains Illuminated				✓			2.5. Electronic Stability Control (ESC)				✓		
2.3a. Brake System Warning Lamp Fails to Illuminate				✓			2.6. Powertrain Warning Lamps				✓		
2.3b. Brake System Warning Lamp Remains Illuminated				✓			2.7. Other Safety Systems				✓		
2.4a. SRS Codes Present				✓									

NOTES:

Section 3 - Interior									
Component	P	F	NA	Component	P	F	NA		
3.1. Doors	✓			3.11. Instrument Panel Lamps	✓				
3.2. Rear View Mirror	✓			3.12. HVAC	✓				
3.3. Sun Visors	✓			3.13. Windshield Wiper and Washer Operation	✓				
3.4. Horn	✓			3.14. Accelerator	✓				
3.5. Seats	✓			3.15. Service Brake Pedal	✓				
3.6. Seatbelts	✓			3.16. Clutch Pedal Assembly			✓		
3.7. Signal Lamp Switch and Indicator	✓			3.17. Park Brake	✓				
3.8. Hazard Lamps	✓			3.18. Neutral Safety Switch Operation	✓				
3.9. Headlamp Switch and High Beam Indicator	✓			3.19. Entertainment Display Lockout			✓		
3.10. Auxiliary Lamp Indicator(s)	✓								

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 4 - Glass								
Component	P	F	NA	Component	P	F	NA	
4.1a. Windshield Marked AS-1, AS-10, or AS-14	✓			4.2b. Side Window Operation	✓			
4.1b. Windshield Condition	✓			4.2c. Side Window Aftermarket Tint	✓			
4.1e. Windshield Tinting / Decals	✓			4.2d. Side Window Visibility (general)	✓			
4.1f. Windshield Visibility (general)	✓			4.3a. Rear Window AS-1, AS-2, AS-3, AS-10, or AS-11	✓			
4.2a. Side Glass Marked AS-1, AS-2, AS-10, or AS-11	✓			4.4a. Other Glass	✓			

NOTES:

Section 5 - Lamps								
Component	P	F	NA	Component	P	F	NA	
5.1. Lamps (general)	✓			5.7. Front Side Reflectors	✓			
5.2. Daytime Running Lamps	✓			5.8. Rear Side Marker Lamps	✓			
5.3. High Mount Brake Lamp	✓			5.9. Rear Side Reflectors	✓			
5.4. Headlamps	✓			5.10. Licence Plate Lamp	✓			
5.5. Auxiliary Lamps	✓			5.11. Emergency Lighting	✓			
5.6. Front Side Marker Lamps	✓							

NOTES:

Section 6 - Exterior, General								
Component	P	F	NA	Component	P	F	NA	
6.1. Fuel Cap	✓			6.3. Bumpers	✓			
6.2. General Body Condition	✓			6.4. Aftermarket Equipment Installation				✓

NOTES:

Section 7 - Under Hood								
Component	P	F	NA	Component	P	F	NA	
7.1. Hood Latch Mechanism	✓			7.7. Clutch Master Cylinder				✓
7.2. Hood Prop / Struts	✓			7.8. Fuel System	✓			
7.3. Remote Starter Operation			✓	7.9. Exhaust Manifold(s)	✓			
7.4. Battery	✓			7.10. Oil Leaks	✓			
7.5. Accessory Belt Drive System	✓			7.11. Engine and Transmission Mounts	✓			
7.6. Brake Master Cylinder	✓							

NOTES:

Section 8 - Steering and Suspension								
Component	P	F	NA	Component	P	F	NA	
8.1. Wheel Bearings	✓			8.8. Steering Gear				✓
8.2. Ball Joints (front and rear)	✓			8.9. Rack & Pinion	✓			
8.3. Tie Rod Ends (inner and outer)	✓			8.10. Power Steering System	✓			
8.4. Pitman Arm			✓	8.11. Control Arms	✓			
8.5. Idler Arm			✓	8.12. Struts and Shocks	✓			
8.6. Steering Stabilizer / Damper			✓	8.13. Springs	✓			
8.7. Steering Shaft Assembly	✓							

NOTES:

MOTOR VEHICLE RECORD OF INSPECTION

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tread Depth- LF:7 mm,RF:7 mm,LR:9 mm,RR:9 mm	✓			9.4. Tire Serial Numbers & Dates of Manufacture	✓		
9.2. Tire Condition (general)	✓			9.5. Wheels	✓		
9.3. Tire Size	✓			9.6. Wheel Nuts and Studs	✓		

NOTES:

Section 10 - Brakes

Component	P	F	NA	Component	P	F	NA
10.1. Brakes (general)	✓			10.6. Park Brake Drum Diameter- LR:N/A mm,RR:N/A mm			✓
10.2. Park Brake Lining- LR:11 mm,RR:11 mm	✓			10.6. Brake Rotor Thickness- LF:32.79 mm,RF:32.67 mm	✓		
10.2. Brake Lining- LF:8 mm,RF:8 mm,LR:11 mm,RR:11 mm	✓			10.7. Brake Drum Condition (general)			✓
10.3. Brake Lines and Hoses	✓			10.8. Brake Rear Rotor- LR:17.84 mm,RR:17.75 mm	✓		
10.4. Brake System Wiring	✓			10.9. Park Brake	✓		
10.5. Brake Rotor Condition (general)	✓						

NOTES:

Section 11 - Under Vehicle

Component	P	F	NA	Component	P	F	NA
11.1. Bumpers	✓			11.5. Drive Axles / Propeller Shafts	✓		
11.2. Engine	✓			11.6. Floor Pan	✓		
11.3. Transmission / Transaxle / Transfer Case	✓			11.7. Fuel System	✓		
11.4. Differential(s)	✓			11.8. Exhaust System	✓		

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED (Certificate #5556123)** the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection 2022/05/10	Technician Number C8925	Facility Number 16639	Signature 
---	-----------------------------------	---------------------------------	--

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2022/05/10

Customer Signature
