

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 20 - 2011 Nissan Quest



VIN JN8AE2KP0B9005827

Year 2011

Make Nissan

Model Quest

Trim Level FWD

Engine 3.5

Transmission AUTOMATIC

Odometer 244,901

Odo Type KM

Color Black

Declaration Engine Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Sunroof, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, CD Player, Subscription Based Satellite Radio, Backup Camera, Rear DVD, Handsfree Calling, Leather Interior

Air Conditioning / Heat (Jardine) AC Not Functioning, Heat Functioning

Comments WARNING LIGHTS - TIRE PRESSURE, CHECK ENGINE

Location Fredericton NB - Jardine

Tires Front 3/32, Rear 5/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 12/25

Plate Number (Jardine) KGW 931

MVI (Jardine) 06/27

Interior Comments (Jardine) Headliner/seat/floor stains. Leather torn throughout vehicle. Carpet stains. *AC not functioning.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips. Majority of vehicle paint touched up. Front left fender dents/wheel liner ripped. Left rear door rust. Left rear fender rust. Rear bumper scuffs. Trunk rust. Right rear fender rust. Front right door plastic trim peeling. Front bumper paint peeling. Roof rust. Windshield chips.

Exterior Condition (Jardine) Good

Description

***AC not functioning**

[CARFAX; COLLISION CLAIMS \\$697, \\$1,074, \\$2,677; MISC. CLAIM \\$3,109; PREVIOUS AUCTIONS ANNOUNCED AS ACCIDENT REPAIR, & FLEET/LEASE VEHICLE; PREVIOUS PERSONAL USE NOTED](#)

Vin JN8AE2KP0B9005827

Year 2011

Make Nissan

Model Quest

Trim FWD

Engine 3.5

Transmission AUTOMATIC

Odometer 244,901, KM

Color Black

Declaration Engine Light On

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Sunroof, Tilt, Sunroof, Roof Rails / Rack, Heated Setas, CD Player, Subscription Based Satellite Radio, Backup Camera, Rear DVD, Handsfree Calling, Leather Interior

Air Conditioning / Heat (Jardine) AC Not Functioning, Heat Functioning

Comments WARNING LIGHTS - TIRE PRESSURE, CHECK ENGINE

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 3/32, Rear 5/32

Sales Status Red Light - Sold AS IS

Plate Date 12/25

Plate Number KGW 931

MVI 06/27

Interior Comments Headliner/seat/floor stains. Leather torn throughout vehicle. Carpet stains. *AC not functioning.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips. Majority of vehicle paint touched up. Front left fender dents/wheel liner ripped. Left rear door rust. Left rear fender rust. Rear bumper scuffs. Trunk rust. Right rear fender rust. Front right door plastic trim peeling. Front bumper paint peeling. Roof rust. Windshield chips.

Exterior Condition Good

Quantity: 1