

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 1 - 2012 Ford Focus SE



VIN 1FAHP3F2XCL121524

Year 2012

Make Ford

Model Focus

Trim Level FWD

Engine 2.0L I4 160hp 146ft. lbs.

Transmission Automatic

Odometer 156 186

Odo Type KM

Color White

Declaration Engine Light On, Requires Boost

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments TRUNK DOES NOT OPEN, VEHICLE REQUIRES BOOST

Location Fredericton NB - Jardine

Tires Front 6/32 rear 6/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) NONE

Plate Number (Jardine) NONE

MVI (Jardine) 05/26

Interior Comments (Jardine) Headliner/seats/floor stains, dirt/dust, cable in back seat

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left door rust/inner door rust, rear left door rust/inner door rust/doorsill dents, left rocker rust/holes, left rear fender rust, trunk rust, right rear fender rust, right rocker rust/holes, right rear inner door rust, front right door rust/inner door rust, front right fender dents, hood paint peel/rust/dents, roof rust, tailgate reflective strip, front right hubcap chip, windshield chips

Exterior Condition (Jardine) Fair

Description

VEHICLE REQUIRES BOOST

CLEAN CARFAX

VIN 1FAHP3F2XCL121524

Year 2012

Make Ford

Model Focus

Trim FWD

Engine 2.0L I4 160hp 146ft. lbs.

Transmission Automatic

Odometer: 156 186, KM

Color White

Declaration Engine Light On, Requires Boost

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments TRUNK DOES NOT OPEN, VEHICLE REQUIRES BOOST

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 6/32 rear 6/32

Sales Status Red Light - Sold AS IS

Plate Date NONE

Plate Number NONE

MVI 05/26

Interior Comments Headliner/seats/floor stains, dirt/dust, cable in back seat

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left door rust/inner door rust, rear left door rust/inner door rust/doorsill dents, left rocker rust/holes, left rear fender rust, trunk rust, right rear fender rust, right rocker rust/holes, right rear inner door rust, front right door rust/inner door rust, front right fender dents, hood paint peel/rust/dents, roof rust, tailgate reflective strip, front right hubcap chip, windshield chips

Exterior Condition Fair

Quantity: 1