

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 7 - 2009 Ford Focus SE



VIN 1FAHP35N29W214699

Year 2009

Make Ford

Model Focus

Trim Level FWD

Engine 2.0L I4 140hp 136ft. lbs.

Transmission Automatic

Odometer 150 201

Odo Type KM

Color White

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Alum Rims, CD Player, Subscription Based Satellite Radio, Handsfree Calling, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Not Functioning, Heat Functioning

Comments IDLES SLIGHTLY ROUGH

Location Fredericton NB - Jardine

Tires Front 8/32 rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 10/19

Plate Number (Jardine) GWB 237

MVI (Jardine) 12/26

Interior Comments (Jardine) Headliner/seats/floor stains

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left fender dents, left rocker redone, front left doorsill dents, rear left inner door rust, rear left fender

repainted, right rear fender dents, right rocker redone, right rear door dents, windshield chips

Exterior Condition (Jardine) Good

Description

IDLES SLIGHTLY ROUGH

[CLEAN CARFAX](#)

VIN 1FAHP35N29W214699

Year 2009

Make Ford

Model Focus

Trim FWD

Engine 2.0L I4 140hp 136ft. lbs.

Transmission Automatic

Odometer: 150 201, KM

Color White

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Alum Rims, CD Player, Subscription Based Satellite Radio, Handsfree Calling, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Not Functioning, Heat Functioning

Comments IDLES SLIGHTLY ROUGH

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 8/32 rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date 10/19

Plate Number GWB 237

MVI 12/26

Interior Comments Headliner/seats/floor stains

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left fender dents, left rocker redone, front left doorsill dents, rear left inner door rust, rear left fender repainted, right rear fender dents, right rocker redone, right rear door dents, windshield chips

Exterior Condition Good

Quantity: 1



<https://www.jardineauctioneers.com/>