

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 25 - 2011 Honda CR-V AWD EX-L 4dr SUV



VIN 5J6RE4H78BL816032

Year 2011

Make Honda

Model CR-V

Trim Level AWD EX-L 4dr SUV

Engine 2.4L I4 180hp 161ft. lbs.

Transmission Automatic

Odometer 340 007

Odo Type KM

Color Silver

Declaration Engine Light On, Vehicle Loud - Possible Exhaust Leak

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Engine light, TPMS, low washer fluid.

Location Fredericton NB - Jardine

Tires Front 5/32, rear 01/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 09/25

Plate Number (Jardine) JPV 083

MVI (Jardine) 07/26

Interior Comments (Jardine) Headliner/seats/carpet stains, radio needs code to function.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips/rust stains, front left door sill rust/inner door rust, rear left door sill dents, trunk dents/rust, right rear door dents/door sill rust/inner door rust, front right door sill dents/inner door rust, headlights fogged, hood dents, windshield chips.

Exterior Condition (Jardine) Good

Description

Vehicle runs rough, noise coming from engine bay

[CARFAX; 2 COLLISION CLAIMS \\$4730 & \\$0, OTHER DAMAGE CLAIM \\$807](#)

VIN 5J6RE4H78BL816032

Year 2011

Make Honda

Model CR-V

Trim AWD EX-L 4dr SUV

Engine 2.4L I4 180hp 161ft. lbs.

Transmission Automatic

Odometer: 340 007, KM

Color Silver

Declaration Engine Light On, Vehicle Loud - Possible Exhaust Leak

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: Engine light, TPMS, low washer fluid.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 5/32, rear 01/32

Sales Status Red Light - Sold AS IS

Plate Date 09/25

Plate Number JPV 083

MVI 07/26

Interior Comments Headliner/seats/carpet stains, radio needs code to function.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips/rust stains, front left door sill rust/inner door rust, rear left door sill dents, trunk dents/rust, right rear door dents/door sill rust/inner door rust, front right door sill dents/inner door rust, headlights fogged, hood dents, windshield chips.

Exterior Condition Good

Quantity: 1

