

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 27 - 2008 Buick Allure CX



VIN 2G4WF582881178052

Year 2008

Make Buick

Model Allure

Trim Level FWD

Engine 3.8

Transmission Automatic

Odometer 135,898

Odo Type KM

Color White

Declaration Engine Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Heated Seats, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning Lights: tire pressure monitoring system, engine light

Location Fredericton NB - Jardine

Tires Front 6/32 rear 6/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 01/25

Plate Number (Jardine) JGX 179

MVI (Jardine) 04/26

Interior Comments (Jardine) Headliner/seats/carpet stains

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips/rust stains, front left door dents/scuffs, rear left inner door rust, rear left fender rust/gas cap very loose/rusted out, rear bumper residue/gouges/paint peeling/cracks, trunk scuffs, right rear door scuffs, front right door scuffs, front right fender paint peeling/rust, front bumper gouges, headlights fogged, hood scuffs,

Exterior Condition (Jardine) Good

Description

[CARFAX; COLLISION CLAIM LEFTREAR REAR \\$2912](#)

VIN 2G4WF582881178052

Year 2008

Make Buick

Model Allure

Trim FWD

Engine 3.8

Transmission Automatic

Odometer: 135,898, KM

Color White

Declaration Engine Light On

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Heated Seats, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning Lights: tire pressure monitoring system, engine light

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 6/32 rear 6/32

Sales Status Red Light - Sold AS IS

Plate Date 01/25

Plate Number JGX 179

MVI 04/26

Interior Comments Headliner/seats/carpet stains

Interior Condition Good

Exterior Comments Multiple scratches/paint chips/rust stains, front left door dents/scuffs, rear left inner door rust, rear left fender rust/gas cap very loose/rusted out, rear bumper residue/gouges/paint peeling/cracks, trunk scuffs, right rear door scuffs, front right door scuffs, front right fender paint peeling/rust, front bumper gouges, headlights fogged, hood scuffs,

Exterior Condition Good

Quantity: 1



<https://www.jardineauctioneers.com/>