

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 44 - 2015 Volvo XC60 T6 AWD



VIN YV4902RC4F2572389

Year 2015

Make Volvo

Model XC60

Trim Level T6 AWD

Engine 3.0L Turbo I6 300hp 325ft. lbs.

Transmission Automatic

Odometer 343 330

Odo Type KM

Color White

Declaration Engine Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Alum Rims, CD Player, Bluetooth, Backup Camera, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Check engine, ABS, traction control.

Location Fredericton NB - Jardine

Tires Front 6/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 06/26

Plate Number (Jardine) NDU 858

MVI (Jardine) 03/27

Interior Comments (Jardine) Headliner/seats/floor stains, shifter cracked, several warning lights.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, left rear doorsill dents, left rear fender dents, front right fender repainted, hood repainted, windshield chips.

Exterior Condition (Jardine) Good

Description

[CARFAX - Collision claim \\$5,128](#)

VIN YV4902RC4F2572389

Year 2015

Make Volvo

Model XC60

Trim T6 AWD

Engine 3.0L Turbo I6 300hp 325ft. lbs.

Transmission Automatic

Odometer: 343 330, KM

Color White

Declaration Engine Light On

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Alum Rims, CD Player, Bluetooth, Backup Camera, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: Check engine, ABS, traction control.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 6/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date 06/26

Plate Number NDU 858

MVI 03/27

Interior Comments Headliner/seats/floor stains, shifter cracked, several warning lights.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, left rear doorsill dents, left rear fender dents, front right fender repainted, hood repainted, windshield chips.

Exterior Condition Good

Quantity: 1



[**https://www.jardineauctioneers.com/**](https://www.jardineauctioneers.com/)