

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 49 - 2016 Honda CR-V



VIN 2HKRM4H55GH106816

Year 2016

Make Honda

Model CR-V

Engine 2.4L I4 185hp 181ft. lbs.

Transmission Automatic

Odometer 257 431

Odo Type KM

Color White

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Heated Mirrors, Alum Rims, Hitch, CD Player, Bluetooth, Backup Camera, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Location Fredericton NB - Jardine

Tires Front 8/32 rear 11/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 06/26

Plate Number (Jardine) JMT 492

MVI (Jardine) 10/27

Interior Comments (Jardine) Headliner/seats/carpet stains

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips/rust stains, front left inner door rust, rear bumper scuffs, trunk rust, right rear door paint touch ups, front right inner door rust, front bumper scuffs/gouges/paint touch ups,

Exterior Condition (Jardine) Good

Description

[CARFAX; COLLISION FRONT CLAIM \\$9332](#)

VIN 2HKRM4H55GH106816

Year 2016

Make Honda

Model CR-V

Engine 2.4L I4 185hp 181ft. lbs.

Transmission Automatic

Odometer: 257 431, KM

Color White

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Heated Mirrors, Alum Rims, Hitch, CD Player, Bluetooth, Backup Camera, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 8/32 rear 11/32

Sales Status Red Light - Sold AS IS

Plate Date 06/26

Plate Number JMT 492

MVI 10/27

Interior Comments Headliner/seats/carpet stains

Interior Condition Good

Exterior Comments Multiple scratches/paint chips/rust stains, front left inner door rust, rear bumper scuffs, trunk rust, right rear door paint touch ups, front right inner door rust, front bumper scuffs/gouges/paint touch ups,

Exterior Condition Good

Quantity: 1



<https://www.jardineauctioneers.com/>