

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 56 - 2011 Ford Fusion Hybrid



VIN 3FADP0L35BR118458

Year 2011

Make Ford

Model Fusion Hybrid

Trim Level FWD

Engine 2.5L Hybrid I4 191hp

Transmission AUTOMATIC

Odometer 207 873

Odo Type KM

Color White

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Handsfree Calling, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Low tire pressure, tire pressure sensor fault.

Location Fredericton NB - Jardine

Tires Front 4/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 10/25

Plate Number (Jardine) GZY 515

MVI (Jardine) 02/26

Interior Comments (Jardine) Headliner/carpet stains.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips/rust stains, front left fender paint peeling/repainted, front left inner door rust, rear left door sill dents/repainted/inner door rust, left rocker paint peeling/repainted, rear left fender repainted/paint peeling/rust, rear bumper over spray/gouges, trunk paint peeling/rust/repainted, right rear fender paint peeling/repainted, right rocker paint peeling/repainted, right rear inner door rust, front right fender paint peeling/repainted, roof paint bubbling/rust, windshield chips.

Exterior Condition (Jardine) Good

Description

Warning lights: Low tire pressure, tire pressure sensor fault.

CLEAN CARFAX

VIN 3FADP0L35BR118458

Year 2011

Make Ford

Model Fusion Hybrid

Trim FWD

Engine 2.5L Hybrid I4 191hp

Transmission AUTOMATIC

Odometer: 207 873, KM

Color White

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Handsfree Calling, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: Low tire pressure, tire pressure sensor fault.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 4/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date 10/25

Plate Number GZY 515

MVI 02/26

Interior Comments Headliner/carpet stains.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips/rust stains, front left fender paint peeling/repainted, front left inner door rust, rear left door sill dents/repainted/inner door rust, left rocker paint peeling/repainted, rear left fender repainted/paint peeling/rust, rear bumper over spray/gouges, trunk paint peeling/rust/repainted, right rear fender paint peeling/repainted, right rocker paint peeling/repainted, right rear inner door rust, front right fender paint peeling/repainted, roof paint bubbling/rust, windshield chips.

Exterior Condition Good

Quantity: 1