

Sale Name: October 17, 2025 - Automotive Timed & Live Vehicles & RV's - New Brunswick

LOT 22 - 2008 Ford Edge Limited- AWD



VIN 2FMDK49CX8BB18269

Year 2008

Make Ford

Model Edge

Trim Level AWD

Engine 3.5L V6 265hp 250ft. lbs.

Transmission Automatic

Odometer 198 966

Odo Type KM

Color Grey

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, Electric Tailgate, CD Player, Handsfree Calling, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: tire pressure and seat belt

Location Fredericton NB - Jardine

Tires Front 7/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) None

Plate Number (Jardine) None

MVI (Jardine) None

Interior Comments (Jardine) Headliner stains.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left door paint bubbling/scuffs/door sill rust/inner door rust, rear left door sill repainted/inner door

rust, rear left fender repaired/repainted, trunk repainted, right rear inner door rust, front right inner door rust, front right fender repainted, roof paint bubbling/rust

Exterior Condition (Jardine) Good

Description

[CARFAX; OTHER DAMAGE CLAIM \\$77, COLLISION CLAIM \\$7150, PREVIOUS AUCTION ANNOUNCED AS ACCIDENT REPAIR](#)

VIN 2FMDK49CX8BB18269

Year 2008

Make Ford

Model Edge

Trim AWD

Engine 3.5L V6 265hp 250ft. lbs.

Transmission Automatic

Odometer: 198 966, KM

Color Grey

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, Electric Tailgate, CD Player, Handsfree Calling, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: tire pressure and seat belt

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 7/32

Sales Status Red Light - Sold AS IS

Plate Date None

Plate Number None

MVI None

Interior Comments Headliner stains.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left door paint bubbling/ scuffs/door sill rust/inner door rust, rear left door sill repainted/inner door rust, rear left fender repaired/repainted, trunk repainted, right rear inner door rust, front right inner door rust, front right fender repainted, roof paint bubbling/rust

Exterior Condition Good

Quantity: 1



<https://www.jardineauctioneers.com/>