

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 40 - 2012 Audi Q5



VIN WA1LFCFP7CA068449

Year 2012

Make Audi

Model Q5

Trim Level AWD

Engine 2.0

Transmission Automatic

Odometer 287 270

Odo Type KM

Color White

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Low tire pressure, low fuel.

Location Fredericton NB - Jardine

Tires Front 6/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 01/26

Plate Number (Jardine) NDP 306

MVI (Jardine) 08/27

Interior Comments (Jardine) Clean.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips/rust stains, front left fender paint peeling/rust/repainted, rear left inner door rust, rear left fender paint

bubbling/rust, right rear fender paint bubbling/rust, right rear inner door rust, front right fender paint peeling/rust, front bumper cracks/scuffs, hood dents.

Exterior Condition (Jardine) Good

Description

[CLEAN CARFAX](#)

VIN WA1LFCFP7CA068449

Year 2012

Make Audi

Model Q5

Trim AWD

Engine 2.0

Transmission Automatic

Odometer: 287 270, KM

Color White

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: Low tire pressure, low fuel.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 6/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date 01/26

Plate Number NDP 306

MVI 08/27

Interior Comments Clean.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips/rust stains, front left fender paint peeling/rust/repainted, rear left inner door rust, rear left fender paint bubbling/rust, right rear fender paint bubbling/rust, right rear inner door rust, front right fender paint peeling/rust, front bumper cracks/scuffs, hood dents.

Exterior Condition Good

Quantity: 1