Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick

LOT 54 - 2015 Ford Escape SE AWD



VIN 1FMCU9GX1FUA33403

Year 2015

Make Ford

Model Escape

Trim Level SE AWD

Engine EcoBoost 1.6L Turbo I4 178hp 184ft. lbs.

Transmission Automatic

Odometer 206 379

Odo Type KM

Color Blue

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Tilt, Alum Rims, CD Player, Subscription Based Satellite Radio, Bluetooth, Backup Camera, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Low fuel.

Location Fredericton NB - Jardine

Tires Front 10/32, rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 02/26

Plate Number (Jardine) JJE 535

MVI (Jardine) 09/27

Interior Comments (Jardine) Headliner/seats/floor stains.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left doorsill dents, rear left doorsill dents/inner door rust, rear left fender dents, right rear fender

dents, right rear door dents/inner door rust, front right door dents/doorsill dents, windshield chips.

Exterior Condition (Jardine) Good

Description

CARFAX - Collision claim \$3,774, Unknown claim \$11,257

VIN 1FMCU9GX1FUA33403

Year 2015

Make Ford

Model Escape

Trim SE AWD

Engine EcoBoost 1.6L Turbo I4 178hp 184ft. lbs.

Transmission Automatic **Odometer:** 206 379, KM

Color Blue

Features Power Windows, Power Locks, Power Mirrors, Tilt, Alum Rims, CD Player, Subscription Based Satellite Radio, Bluetooth, Backup Camera, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: Low fuel. **Location** Fredericton NB - Jardine

In Yard Yes

Tires Front 10/32, rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date 02/26

Plate Number JJE 535

MVI 09/27

Interior Comments Headliner/seats/floor stains.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left doorsill dents, rear left doorsill dents/inner door rust, rear left fender dents, right rear fender dents, right rear door dents/inner door rust, front right door dents/doorsill dents, windshield chips.

Exterior Condition Good

Quantity: 1



https://www.jardineauctioneers.com/