

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 39 - 2015 Dodge Grand Caravan



VIN 2C4RDGBG2FR567548

Year 2015

Make Dodge

Model Grand Caravan

Trim Level FWD

Engine Pentastar 3.6L Flex Fuel V6 283hp 260ft. lbs.

Transmission Automatic

Odometer 178 785

Odo Type KM

Color Grey

Declaration Engine Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Heated Mirrors, CD Player, Subscription Based Satellite Radio, Handsfree Calling, Cloth Interior, Stow N Go

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Low fuel.

Location Fredericton NB - Jardine

Tires Front 10/32, rear 8/32, studded tires not on rims in rear of vehicle

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) None

Plate Number (Jardine) None

MVI (Jardine) 04/27

Interior Comments (Jardine) Headliner/seats stains, seat tears.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left fender repaired/repainted, rear bumper scuffs, right tail light broken, right rear fender paint bubbling, roof paint bubbling.

Exterior Condition (Jardine) Good

Description

[CARFAX - 2 Collision claims, \\$4,853 & \\$6,692](#)

Vin 2C4RDGBG2FR567548

Year 2015

Make Dodge

Model Grand Caravan

Trim FWD

Engine Pentastar 3.6L Flex Fuel V6 283hp 260ft. lbs.

Transmission Automatic

Odometer 178 785, KM

Color Grey

Declaration Engine Light On

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Heated Mirrors, CD Player, Subscription Based Satellite Radio, Handsfree Calling, Cloth Interior, Stow N Go

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Low fuel.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 10/32, rear 8/32, studded tires not on rims in rear of vehicle

Sales Status Red Light - Sold AS IS

Plate Date None

Plate Number None

MVI 04/27

Interior Comments Headliner/seats stains, seat tears.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left fender repaired/repainted, rear bumper scuffs, right tail light broken, right rear fender paint bubbling, roof paint bubbling.

Exterior Condition Good

Quantity: 1

