

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 33 - 2012 Volkswagen CC 2.0T



VIN WVWMN9AN6CE525699

Year 2012

Make Volkswagen

Model CC

Trim Level 2WD

Engine 2.0T

Transmission Automatic

Odometer 154 018

Odo Type KM

Color Black

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Bluetooth, Handsfree Calling, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Location Fredericton NB - Jardine

Tires Front 4/32, rear 5/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 12/25

Plate Number (Jardine) KCU 279

MVI (Jardine) 09/26

Interior Comments (Jardine) Headliner/carpet stains.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left fender paint bubbling/rust, rear left window not fully closing, rear left fender paint bubbling/rust,

right rear fender paint bubbling/rust, front right fender paint bubbling/rust, windshield cracks.

Exterior Condition (Jardine) Good

Description

[CLEAN CARFAX](#)

VIN WVWMN9AN6CE525699

Year 2012

Make Volkswagen

Model CC

Trim 2WD

Engine 2.0T

Transmission Automatic

Odometer: 154 018, KM

Color Black

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Bluetooth, Handsfree Calling, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 4/32, rear 5/32

Sales Status Red Light - Sold AS IS

Plate Date 12/25

Plate Number KCU 279

MVI 09/26

Interior Comments Headliner/carpet stains.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left fender paint bubbling/rust, rear left window not fully closing, rear left fender paint bubbling/rust, right rear fender paint bubbling/rust, front right fender paint bubbling/rust, windshield cracks.

Exterior Condition Good

Quantity: 1



<https://www.jardineauctioneers.com/>