

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 10 - 2004 Toyota Highlander V6 4WD



VIN JTEHP21A040017934

Year 2004

Make Toyota

Model Highlander

Trim Level 4WD

Engine 3.3

Transmission Automatic

Odometer 266 052

Odo Type KM

Color Silver

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Roof Rails / Rack, Hitch, CD Player, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Not Functioning, Heat Functioning

Comments Warning lights: Low tire pressure.

Location Fredericton NB - Jardine

Tires Front 6/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 05/26

Plate Number (Jardine) GKL 132

MVI (Jardine) 12/26

Interior Comments (Jardine) Headliner/seats/carpet stains. *Rear windows not rolling up or down.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, left rocker rust, front left inner door rust, rear left door sill rust/inner door rust, rear left fender dents, rear bumper clear coat/paint peeling/repainted, trunk paint bubbling/rust, right rocker

rust, right rear door sill dents/rust/inner door rust, front right door sill dents/rust, headlights fogged.

Exterior Condition (Jardine) Good

Description

***AC not functioning, rear windows not rolling up/down**

Warning lights: Low tire pressure.

[CARFAX; MILEAGE DISCREPANCY NOTED](#)

VIN JTEHP21A040017934

Year 2004

Make Toyota

Model Highlander

Trim 4WD

Engine 3.3

Transmission Automatic

Odometer: 266 052, KM

Color Silver

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Roof Rails / Rack, Hitch, CD Player, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Not Functioning, Heat Functioning

Comments Warning lights: Low tire pressure.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 6/32, rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date 05/26

Plate Number GKL 132

MVI 12/26

Interior Comments Headliner/seats/carpet stains. *Rear windows not rolling up or down.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, left rocker rust, front left inner door rust, rear left door sill rust/inner door rust, rear left fender dents, rear bumper clear coat/paint peeling/repainted, trunk paint bubbling/rust, right rocker rust, right rear door sill dents/rust/inner door rust, front right door sill dents/rust, headlights fogged.

Exterior Condition Good

Quantity: 1

